

# RECALL NOTICE



## Weber Recalls Metal Wire Bristle Grill Brushes Due to Ingestion Hazard

Weber is conducting a voluntary recall of certain metal wire bristle grill brushes as pictured below. Small metal wire bristles can detach from the brushes, adhere to grill grates or food, and be ingested, posing a risk of serious internal injury requiring medical treatment, including surgery.

### Recalled Models



**Model No. 6277**  
Sold 2021-2026



**Model No. 6278**  
Sold 2021-2026



**Model 6493**  
Sold 2013-2021



**Model 6494**  
Sold 2013-2021



**Model 6463**  
Sold 2011-2021



**Model 6464**  
Sold 2011-2021

**Stop using the recalled grill brushes and contact Weber for a FREE replacement cold cleaning nylon bristle brush.**

Consumers should go to <https://www.weberbrushrecall.expertinquiry.com> for more information on confirming eligibility and requesting the replacement brush.

### Contact Weber

Visit <https://www.weberbrushrecall.expertinquiry.com> or call 877-597-9588.